

# BIG BOX RETAIL FOR LEASE

# 2101 W. BROADWAY MONONA, WI

Key Commercial Real Estate LLC | 608-729-1800 | www

The information presented herein is based on estimates and assumptions and is presented for illustration purposes only. No represent

SHOPKO

### **TABLE OF CONTENTS**

Property Details	Pg. 3
Location & Demographics	Pg. 4
Aerial	Pg. 5
Survey	Pg. 6
Floorplan	Pg. 7
Photos	Pg. 8
Building Details	Pg. 9
Broker Disclosure	Pg. 10



### FOR LEASING DETAIL CONTACT:

Jenny Lisak, CCIM O: 608.729.1808 C: 608.513.5447 jlisak@keycomre.com

> Mallory Rekoske O: 608.729.1803 C: 608.469.0384

mrekoske@keycomre.com

Key Commercial Real Estate LLC | 608-729-1800 | www.keycomre.com



## **Property Details**

### **OVERVIEW**


Former Shopko big box now available for lease! This site has unmatched presence along a major highway visible to 117,000 vehicles daily. Adjacent tenants are quality nationals such as Kohl's, Hobby Lobby, Planet Fitness and more. This opportunity is ideal for retail or a creative adaptive reuse of the site .

### HIGHLIGHTS

- Available May 2019
- 97,931 square feet (plus 21,850 sf mezzanine)
- Zoned Community Design District (CDD)
- Located in an Opportunity Zone
- Highly visible location frontage the Beltline Hwy
- Positioned between East and West Madison allows one location to capture 2 markets
- Part of fully leased power center with all nationals
- Can be demised to accommodate 2 tenants
- Second floor mezzanine office
- 6.2:1,000 parking ratio
- Lease Rate: \$6.50/SF NNN
- NNN Estimate: \$3.67 SF
- 2 outlots available for sale
  - Lot 1 (@ \$10.00/sf
  - Lot 2 @ \$8.00/sf



### Key Commercial Real Estate LLC | 608-729-1800 | www.keycomre.com



Page 4


### Key Commercial Real Estate LLC | 608-729-1800 | www.keycomre.com





### Key Commercial Real Estate LLC | 608-729-1800 | www.keycomre.com


Survey



KEYCOMMERCIAL REAL ESTATE, LLC Page 6

### Key Commercial Real Estate LLC | 608-729-1800 | www.keycomre.com

### **Floor Plan**



### **Photos**





















### Key Commercial Real Estate LLC | 608-729-1800 | www.keycomre.com

Number of Stories1Square Footage97,931 SF (plus 21,850 Sf mezzanine)State Coverage Ratio21.9% (10.28 arcs)Parking606 (Surface) 6.2/1,000 SF.Year Balit93 IYear RonotadoConcrete blockFoundationReinforced concrete slabFramingStructural steel with masonry and concrete encasementExterior WallsForcerete blockRoofFast travith store balast cover.HVACForcerete blockCentral HVAC in office 21 rooftop unitsExterior WallsAcoustical tile in the store and exposed concrete block in the warehouse. 21 rooftop unitsExterior WallsAcoustical tile in the store and exposed concrete block in the warehouse. 21 rooftop unitsExterior WallsAcoustical tile in the store and exposed concrete block in the warehouse. 21 rooftop unitsExterior WallsAcoustical tile in the store and exposed concrete block in the warehouse. 21 rooftop unitsExterior WallsAcoustical tile in the store and exposed concrete block in the warehouse. 20 rooftop unitsExterior WallsAcoustical tile in the store and exposed concrete block in the warehouse. 20 rooftop unitsDoors2-8'x 8' dock doorsOverhead doors2-8'x 8'Linding Dock2-8'x 8' dock doorsFree Toreet dockToreet sidewalks, concrete curbing, pole mounted lights and sprinklered landscapingIndicacingChated in Opportunity ZoneCortionChated in Opportunity Zone	Property Type	Retail / Commercial - Free Standing Retail/Commercial Building	<b>Building Details</b>
Site Coverage Ratio21.9% (10.28 acres)Parking606 (Surface) 6.2/1,000 SF.Year Built1981Year Renovated2000Basic ConstructionConcrete blockFoundationReinforced concrete slabFramingStructural steel with masonry and concrete encasementExterior WallsConcrete blockRoofFlat ar with stone ballast cover.HVACConcrete blockRoofFlat ar with stone ballast cover.HVACConcrete block office 2.1 rooftop unitsElectrical1.600 amp, 3 phase electrical serviceInterior WallsPainted plaster in the store and exposed concrete block in the warehouse, 2.1 rooftop unitsElectrical1.600 amp, 3 phase electrical serviceInterior WallsPainted plaster in the store and exposed concrete block in the warehouse, 10" - 24' clear heightDoorsAutomatic double dor system, glass in metal frame Loading DockOors2-8'x 8' dock doorsOurse2-8'x 8'InftUft to second floor mezzanine storageFire ProtectionThe subject has a fire sprinkler system.LindscapingAshalt, concrete sidewalks, concrete curbing, pole mounted lights and sprinklered landscaping.SignageTenan the subliding affixed signage and a pylon sign at the shopping center's entrance.	Number of Stories	1	Bananig Botano
Parking606 (surface) 6.2/1,000 SF.Year Built1981Year Renovated2000Basic ConstructionConcrete blockFoundationReinforced concrete slabFramingStructural steel with masonry and concrete encasementExterior WallsConcrete blockRoofFlat ar with stone ballast cover.HVACCreted Air, hanging units in loading area in warehouse Central HVAC in office 21 rooftop unitsElectrical1,600 amp. 3 phase electrical serviceInterior WallsPainted plaster in the store and exposed concrete block in the warehouse. Central HVAC in office 21 rooftop unitsElectrical1,600 amp. 3 phase electrical serviceInterior WallsPainted plaster in the store and exposed concrete block in the warehouse. 2 S* 8' dock doorsCorst4.to second floor mezzanine storageInterior WallsFa'x 8' dock doorsDors2-8'x 8'LiftLift to second floor mezzanine storageFire ProtectionThe subject has a fire sprinkler system.LindscapingAsphalt, concrete sidewalks, concrete curbing, pole mounted lights and sprinklered landscaping.SignageTeran thas building affiked signage and a pylon sign at the shopping center's entrance.	Square Footage	97,931 SF (plus 21,850 sf mezzanine)	
Year Built1981.Year Renovated2000Basic ConstructionConcrete blockFoundationReinforced concrete slabFramingStructural steel with masonry and concrete encasementExterior WallsConcrete blockRoofFlat tar with stone ballast cover.HVACCentral HVAC in office 21 rooftop unitsElectrical1,600 amp, 3 phase electrical serviceInterior WallsAcoustical tile in the store and exposed concrete block in the warehouse, 10° - 24' clear heightDoorsAutomatic double door system, glass in metal frameLoading Dock2-8'x 8' dock doorsOverhead doors2-8'x 8'LiftLift to second floor mezzanine storageFire ProtectionThe subject has a fire sprinkler system.LindscapingAsphalt, concrete sidewalks, concrete curbing, pole mounted lights and sprinklered landscapingSignageTenant has building affixed signage and a pylon sign at the shopping center's entrance.	Site Coverage Ratio	21.9% (10.28 acres)	
Year Renovated200Basic ConstructionConcrete blockFoundationReinforced concrete slabFramingStructural steel with masonry and concrete encasementExterior WallsConcrete blockRoofFlat tar with stone ballast cover.HVACForced Air, hanging units in loading area in warehouse Cartral HVAC in office 21 rooftop unitsElectrical1,600 amp, 3 phase electrical serviceInterior WallsPainted plaster in the store and exposed concrete block in the warehouse, 10" - 24' clear heightDoorsAutomatic double door system, glass in metal frameLoading Dock2-8'x 8'UftUft to second floor mezzanine storageFire ProtectionThe subject has a fire sprinkler system.LandscapingAsphalt, concrete sidewalks, concrete curbing, pole mounted lights and sprinklered landscapingSignageTennt has building affixed signage and a pylon sign at the shopping center's entrance.	Parking	606 (Surface) 6.2/1,000 SF.	
Basic ConstructionConcrete blockFoundationReinforced concrete slabFramingStructural steel with masonry and concrete encasementExterior WallsConcrete blockRoofFalt tar with stone ballast cover.HVACForced Air, hanging units in loading area in warehouse Central HVAC in office 21 roofop unitsElectrical6,000 amp, 3 phase electrical serviceInterior WallsPointed plaster in the store and exposed concrete block in the warehouse, 10" - 24" clear heightDoorsAutomatic double door system, glass in metal frameLoading Dock2 - 8" x 8"Chref adors2 - 8" x 8"LiftLift to second floor mezzanine storageFire ProtectionThe subject has a fire sprinkler system.LindscapingAphalt, concrete sidewalks, concrete curbing, pole mounted lights and sprinklered landscaping.SignageTenna thas building affixed signage and a pylon sign at the shopping center's entrance.	Year Built	1981	
FoundationReinforced concrete slabFramingStructural steel with masonry and concrete encasementExterior WallsConcrete blockRoofRatt ar with stone ballast cover.HVACForced Air, hanging units in loading area in warehouse Central HVAC in office 21 rooftop unitsElectrical1,600 amp. 3 phase electrical serviceInterior WallsPainted plaster in the store and exposed concrete block in the warehouse, 10" - 24' clear heightCeilingsAutomatic double door system, glass in metal frameLoading Dock2 - 8' x 8'Overhead doors2 - 8' x 8'LiftUs scond floor mezzanine storageFire ProtectionThe subject has a fire sprinkler system.LandscapingAsphalt, concrete sidewalks, concrete curbing, pole mounted lights and sprinklered landscapingSignageCentral the subliding affixed signage and a pylon sign at the shopping center's entrance.	Year Renovated	2000	
FramingStructural steel with masonry and concrete encasementExterior WallsConcrete blockRoofFlat tar with stone ballast cover.HVACForced Air, hanging units in loading area in warehouse Central HVAC in office 21 rooftop unitsElectrical1,600 amp. 3 phase electrical serviceInterior WallsPainted plaster in the store and exposed concrete block in the warehouse, 10" - 24' clear heightDoorsAutomatic double door system, glass in metal frameLeading Dock2-8'x 8' dock doorsOverhead doors2-8'x 8' dock doorsInter OrtectionThe subject has a fire sprinkler system.LandscapingAsphalt, concrete sidewalks, concrete curbing, pole mounted lights and sprinklered landscaping.SignageTenan thas building affixed signage and a pylon sign at the shopping center's entrance.	Basic Construction	Concrete block	
Exterior WallsConcrete blockRoofFlat tar with stone ballast cover.HVACForced Air, hanging units in loading area in warehouse Central HVAC in office 21 rooftop unitsElectrical1,600 amp, 3 phase electrical serviceInterior WallsPainted plaster in the store and exposed concrete block in the warehouse, 10" - 24' clear heightDoorsAcoustical tile in the store and exposed metal frameLoading Dock2-8'x 8' dock doorsOverhead doors2-8'x 8' dock doorsLiftLift os coond floor mezzanine storageFire ProtectionThe subject has a fire sprinkler system.LandscapingAsphalt, concrete sidewalks, concrete curbing, pole mounted lights and sprinklered landscapingSignageTenan thas building affixed signage and a pylon sign at the shoopping center's entrance.	Foundation	Reinforced concrete slab	
RoofFlat tar with stone ballast cover.HVACForced Air, hanging units in loading area in warehouse Central HVAC in office 21 rooftop unitsElectrical1,600 amp, 3 phase electrical serviceInterior WallsPainted plaster in the store and exposed concrete block in the warehouse, 10° - 24' clear heightCeilingsAcoustical tile in the store and exposed metal frame in the warehouse, 10° - 24' clear heightDorsAutomatic double door system, glass in metal frameLoading Dock2-8'x 8' dock doorsOverhead doors2-8' x 8'LiftLift to second floor mezzanine storageFire ProtectionThe subject has a fire sprinkler system.LandscapingAsphalt, concrete sidewalks, concrete curbing, pole mounted lights and sprinklered landscapingSignageTenna thas building affixed signage and a pylon sign at the shopping center's entrance.	Framing	Structural steel with masonry and concrete encasement	
HVACbrcced Air, hanging units in loading area in warehouse Central HVAC in office 21 roofop unitsElectrical6.00 amp, 3 phase electrical serviceInterior WallsPainted plaster in the store and exposed concrete block in the warehouse, 10 and plaster in the store and exposed concrete block in the warehouse, 10" - 24' clear heightCeilingsAcoustical tile in the store and exposed metal frame in the warehouse, 10" - 24' clear heightDorsAutomatic double door system, glass in metal frameLoading Dock2-8' x 8' dock doorsCreifingIf to second floor mezzanine storageIftLift os scond floor mezzanine storageFire ProtectionHe subject has a fire sprinkler system.IandscapingAsphalt, concrete sidewalks, concrete curbing, pole mounted lights and sprinklered landscapingSignageTeam the subliding affixed signage and a pylon sign at the shopping center's entrance.	Exterior Walls	Concrete block	Aller and and
NACCentral HVAC in office 21 rooftop unitsElectrical1,600 amp, 3 phase electrical serviceInterior WallsPainted plaster in the store and exposed concrete block in the warehouseCeilingsAcoustical tile in the store and exposed metal frame in the warehouse, 10" - 24' clear heightDoorsAutomatic double door system, glass in metal frameLoading Dock2- 8' x 8' dock doorsOverhead doors2- 8' x 8'LiftLift to second floor mezzanine storageFire ProtectionThe subject has a fire sprinkler system.LandscapingAsphalt, concrete sidewalks, concrete curbing, pole mounted lights and sprinklered landscapingSignageTenant has building affixed signage and a pylon sign at the shopping center's entrance.	Roof		
Interior WallsPainted plaster in the store and exposed concrete block in the warehouseCeilingsAcoustical tile in the store and exposed metal frame in the warehouse, 10" - 24' clear heightDoorsAutomatic double door system, glass in metal frameLoading Dock2- 8' x 8' dock doorsOverhead doors2- 8' x 8'LiftLift to second floor mezzanine storageFire ProtectionThe subject has a fire sprinkler system.LandscapingAsphalt, concrete sidewalks, concrete curbing, pole mounted lights and sprinklered landscapingSignageTenant has building affixed signage and a pylon sign at the shopping center's entrance.	HVAC	Central HVAC in office	
CeilingsAcoustical tile in the store and exposed metal frame in the warehouse, 10" - 24' clear heightDoorsAutomatic double door system, glass in metal frameLoading Dock2-8' x 8' dock doorsOverhead doors2-8' x 8'LiftLift to second floor mezzanine storageFire ProtectionThe subject has a fire sprinkler system.LandscapingAsphalt, concrete sidewalks, concrete curbing, pole mounted lights and sprinklered landscapingSignageTennt has building affixed signage and a pylon sign at the shopping center's entrance.	Electrical	1,600 amp, 3 phase electrical service	
DoorsAutomatic double door system, glass in metal frameLoading Dock2-8'x 8' dock doorsOverhead doors2-8' x 8'LiftLift to second floor mezzanine storageFire ProtectionThe subject has a fire sprinkler system.LandscapingAsphalt, concrete sidewalks, concrete curbing, pole mounted lights and sprinklered landscapingSignageTenant has building affixed signage and a pylon sign at the shopping center's entrance.	Interior Walls	Painted plaster in the store and exposed concrete block in the warehouse	
Loading Dock2- 8'x 8' dock doorsOverhead doors2- 8' x 8'LiftLift to second floor mezzanine storageFire ProtectionThe subject has a fire sprinkler system.LandscapingAsphalt, concrete sidewalks, concrete curbing, pole mounted lights and sprinklered landscapingSignageTenant has building affixed signage and a pylon sign at the shopping center's entrance.	Ceilings	Acoustical tile in the store and exposed metal frame in the warehouse, 10" - 24' clear he	eight
Overhead doors2-8' x 8'LiftLift to second floor mezzanine storageFire ProtectionThe subject has a fire sprinkler system.LandscapingAsphalt, concrete sidewalks, concrete curbing, pole mounted lights and sprinklered landscapingSignageTenant has building affixed signage and a pylon sign at the shopping center's entrance.	Doors	Automatic double door system, glass in metal frame	
LiftLift to second floor mezzanine storageFire ProtectionThe subject has a fire sprinkler system.LandscapingAsphalt, concrete sidewalks, concrete curbing, pole mounted lights and sprinklered landscapingSignageTenant has building affixed signage and a pylon sign at the shopping center's entrance.	Loading Dock	2– 8'x 8' dock doors	
Fire ProtectionThe subject has a fire sprinkler system.LandscapingAsphalt, concrete sidewalks, concrete curbing, pole mounted lights and sprinklered landscapingSignageTenant has building affixed signage and a pylon sign at the shopping center's entrance.	Overhead doors	2- 8' x 8'	Monona
Landscaping Asphalt, concrete sidewalks, concrete curbing, pole mounted lights and sprinklered landscaping   Signage Tenant has building affixed signage and a pylon sign at the shopping center's entrance.	Lift	Lift to second floor mezzanine storage	
Signage Tenant has building affixed signage and a pylon sign at the shopping center's entrance.	Fire Protection	The subject has a fire sprinkler system.	
	Landscaping	Asphalt, concrete sidewalks, concrete curbing, pole mounted lights and sprinklered land	Iscaping
Location Located in Opportunity Zone	Signage	Tenant has building affixed signage and a pylon sign at the shopping center's entrance.	Concerned Discourse 11
	Location	Located in Opportunity Zone	

KEYCOMMERCIAL REAL ESTATE, LLC

Page 8

### Key Commercial Real Estate LLC | 608-729-1800 | www.keycomre.com

# **BROKER DISCLOSURE TO NON-RESIDENTIAL CUSTOMERS**

Prior to negotiating on your behalf the Broker must provide you the following disclosure statement:

BROKER DISCLOSURE TO CUSTOMERS You are a customer of the transaction or a subagent of another broker who is the agent of another party in the transaction. The broker, or a salesperson acting on behalf of the broker, may provide brokerage services to you. Whenever the broker is providing brokerage services to you, the broker owes you, the customer, the 

- The duty to provide brokerage services to you fairly and honestly. following duties:
- The duty to exercise reasonable skill and care in providing brokerage services to you.
- The duty to provide you with accurate information about market conditions within a reasonable time if you request it, unless disclosure of the information is prohibited by law.
- The duty to disclose to you in writing certain material adverse facts about a property, unless disclosure of the information is prohibited by law (See Lines 47-55). Ξ
- The duty to protect your confidentiality. Unless the law requires it, the broker will not disclose your confidential information or the confidential information of other parties (See Lines 22-39). 12 13 15 16
  - The duty to safeguard trust funds and other property the broker holds.
- The duty, when negotiating, to present contract proposals in an objective and unbiased manner and disclose the advantages and disadvantages of the proposals. 17
- Please review this information carefully. A broker or salesperson can answer your questions about brokerage services, but if you need legal advice, tax advice, or a professional home inspection, contact an attorney, tax advisor, or home inspector 18
  - This disclosure is required by section 452.135 of the Wisconsin statutes and is for information only. It is a plain-language summary of 19 20
- a broker's duties to a customer under section 452.133 (1) of the Wisconsin statutes.

# CONFIDENTIALITY NOTICE TO CUSTOMERS

BROKER WILL KEEP CONFIDENTIAL ANY INFORMATION GIVEN TO BROKER IN CONFIDENCE, OR ANY INFORMATION OBTAINED BY BROKER THAT HE OR SHE KNOWS A REASONABLE PERSON WOULD WANT TO BE KEPT CONFIDENTIAL, UNLESS THE INFORMATION MUST BE DISCLOSED BY LAW OR YOU AUTHORIZE THE BROKER TO DISCLOSE PARTICULAR INFORMATION. A BROKER SHALL CONTINUE TO KEEP THE INFORMATION CONFIDENTIAL AFTER BROKER IS NO LONGER 

- THE FOLLOWING INFORMATION IS REQUIRED TO BE DISCLOSED BY LAW: PROVIDING BROKERAGE SERVICES TO YOU.
- 1. MATERIAL ADVERSE FACTS, AS DEFINED IN SECTION 452.01 (59) OF THE WISCONSIN STATUTES (SEE LINES 47-55).
- 2. ANY FACTS KNOWN BY THE BROKER THAT CONTRADICT ANY INFORMATION INCLUDED IN A WRITTEN INSPECTION REPORT ON THE PROPERTY OR REAL ESTATE THAT IS THE SUBJECT OF THE TRANSACTION.
- TO ENSURE THAT THE BROKER IS AWARE OF WHAT SPECIFIC INFORMATION YOU CONSIDER CONFIDENTIAL, YOU MAY LIST THAT INFORMATION BELOW (SEE LINES 35-36). AT A LATER TIME, YOU MAY ALSO PROVIDE THE BROKER WITH OTHER
  - INFORMATION YOU CONSIDER TO BE CONFIDENTIAL.
    - CONFIDENTIAL INFORMATION:

NON-CONFIDENTIAL INFORMATION (The following information may be disclosed by Broker): 36 37 38

INSERT INFORMATION YOU AUTHORIZE THE BROKER TO DISCLOSE SUCH AS FINANCIAL QUALIFICATION INFORMATION.) 39

CONSENT TO TELEPHONE SOLICITATION 40

l/we I/We agree that the Broker and any affiliated settlement service providers (for example, a mortgage company or title company) may call our/my home or cell phone numbers regarding issues, goods and services related to the real estate transaction until 41

withdraw this consent in writing. List Home/Cell Numbers: 42 43

SEX OFFENDER REGISTRY 44

Notice: You may obtain information about the sex offender registry and persons registered with the registry by contacting the Wisconsin Department of Corrections on the Internet at: http://offender.doc.state.wi.us/public/ or by phone at 608-240-5830. 45 46

**DEFINITION OF MATERIAL ADVERSE FACTS** 47

A "material adverse fact" is defined in Wis. Stat. § 452.01(5g) as an adverse fact that a party indicates is of such significance, or that is generally recognized by a competent licensee as being of such significance to a reasonable party, that it affects or would affect the party's decision to enter into a contract or agreement concerning a transaction or affects or would affect the party's decision about the terms of such a contract or agreement. An "adverse fact" is defined in Wis. Stat. § 452.01(1e) as a condition or occurrence 48 49 50 51

that a competent licensee generally recognizes will significantly and adversely affect the value of the property, significantly reduce 52

that indicates that a party to a transaction is not able to or does not intend to meet his or her obligations under a contract or the structural integrity of improvements to real estate, or present a significant health risk to occupants of the property; or information 53 55

No representation is made as to the legal validity of any provision or the adequacy of any provision in any specific transaction. Copyright 2007 by Wisconsin REALTORS® Association agreement made concerning the transaction.

Broker Disclo Key Commercial Real Estate LLC, 305 S. Paterson Street Madison, WI 53703 Deborah Ersland Deborah Ersland

Drafted by Attorney Debra Peterson Conrad