

811 Walsh Road #2, Madison, WI

Seller disclosure Page 5

B6: The brick façade on the front of the building needs to be repaired and re-secured to the building.  
The condo association is responsible for the repair.

The service door has rust on it.